

The changes in V28271 address disruptions in the transport stream artificially induced due to software issues. Weak signal messages may still occur:

- 1) During channel change
- 2) During video/audio dropouts from the source

1.1.29111

- Initial Colossus Release
- Added new configuration tool
- Fixed bug causing wrong channel number to be blasted after several days of operation

1.2.29157

- Fixed bug causing audio to be lost on a channel change when using the "optical" audio input.
- Fixed BSOD during channel change on certain 64-bit systems.

1.2.29178

- Modifications to eliminate the "Weak Signal" messages when changing channels with the HDPVR.

1.2.29271

- Modifications to eliminate audio loss when changing channels with Colossus.